







May 2006: Coir logs were installed above the gully to halt flood erosion



May 2006: The outfall structure was armoured against further erosion





May 2010: The outfall is now completely protected from erosion



May 2010: Extensive sediment accretion has occurred and erosion repaired.